

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015321**Date Inspected:** 29-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	Mr. Xu Le Feng/ Mr. Gao Zhi Chun			CWI Present:	Yes	No
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No N/A
				Delayed / Cancelled:	Yes	No N/A
Bridge No:	34-0006			Component:	Tower	

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance(QA) Inspector, Baskar Govindarajan, was present during the times noted above for observations relative to the work being performed.

Tower Jetty

1. This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 040582 perform SMAW Repair welding on; Cross bracing connecting plate in south shaft at Tower trial assembly area in 65 mtr. elevation and the weld joint is identified as SSD1-SA164 C/F-11. ZPMC CWI Identified as Mr. Zhao Chen Sun. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-345+485-SMAW-2G (2F)-FCM-Repair.

Bay no. 10

2. This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 052075 perform FCAW welding on; Façade plate manhole plate and the weld joint is identified as SD1-SFSA3-38-3, 9. ZPMC CWI Identified as Mr. Gao Zhi Chun. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2132.

3. This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 056200 perform SMAW Repair welding on; North shaft, Lift 5, Transverse diaphragm plate with Skin A, and the weld joint is identified as NSD1-TL5-3B/F-24B. ZPMC CWI Identified as Mr. Gao Zhi Chun. The welding parameters

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

as measured using QC's calibrated instruments appeared to be in general compliance with WPS-485-SMAW-3G (3F)-Repair. (Photo attached)

Bay no. 11

4.This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 067610 perform SMAW welding on; Grating support bracket on West Tower, Lift 4, 116 mtr. elevation and the weld joint is identified as GGSA-69 PLAN-116mtr.-3-3,4. ZPMC CWI Identified as Mr. Xu Le Feng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-2114. (Photo attached)

5.This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 040614 perform SMAW welding on; Lift 4 to 5, interior splice plate and the weld joint is identified as ESD1-SPSA5-12-1A. ZPMC CWI Identified as Mr. Xu Le Feng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-3211-TC-U5B-1

6.This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 046704 perform SMAW welding on; Lift 4 to 5, interior splice plate and the weld joint is identified as WSD1-SPSA5-12-1A. ZPMC CWI Identified as Mr. Xu Le Feng. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-3211-TC-U5B-1

7.This QA inspector, Baskar Govindarajan, observed, ZPMC qualified welding personnel identified as 202100 / 040619 perform SMAW welding on; Spare strut Web to stiffener and the weld joint is identified as WD1-STSA4-5-131mtr.-1-56, 38. ZPMC CWI Identified as Mr. Yu Dong Ping. The welding parameters as measured using QC's calibrated instruments appeared to be in general compliance with WPS-B-T-4113.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Micheal Ng (15921845703), who represents the Office of Structural Materials for your project.

Inspected By:	Baskar, Govindarajan	Quality Assurance Inspector
----------------------	----------------------	-----------------------------

Reviewed By:	Clifford, William	QA Reviewer
---------------------	-------------------	-------------